

**Technical Specification**




|                       |  |
|-----------------------|--|
| Model                 | LD 1252  |
| Display               | Upper : 5 digit, 7 seg 0.56" RED LED<br>Lower : 5 digit, 7 seg 0.56" WHITE LED |
| Size(mm)              | 101 (H) x 101 (W) x 54 (D)mm   |
| Panel Cutout          | 92X92mm  |
| Input                 | 0 to 20mV DC   |
| Output                | 1R1C/O & 10V DC Excitation Voltage   |
| Power Supply          | 100-270VAC(SMPS)   |
| Protection Level      | IP-65 (Front side) As per IS/IEC 60529 : 2001                                  |
| Operating Temperature | 0°C To 55°C  |
| Relative Humidity     | Up to 95% RH Non Condition   |

**Calibration Method**

- 1) Suppose, you have 5Kg load on the cell. You can set the 5 Ckg (Calibration Kg) parameter on the load cell.
- 2) Press **SET** Key, display will indicate message for HCAL (Higher Calibration).
- 3) Now remove the load, press **SET** key, display will indicate for LCAL (Lower Calibration).

**Connection Diagram**



# Basic Configuration


Press  Key

 Set Point 1

 Range : 0.0 to 9999.9

Press  Key

 Hysteresis 1

 0.1-99.9

Press  Key

 Alarm mode 1

 (Low Alarm & High Alarm)

Press  Key

 Decimal Point

 Range : 0.0000 To 00000

Select decimal point as per requirement as shown as follow.


For ex.1kg load

Decimal sele. type  →


Decimal sele. type  →

↓ Press  Key


Customer have to put minimum 20% to 25% load of Load cell value. Put load on load cell & enter the value of load in Ckg parameter.



Next parameter is H-CAL some counter is display as per load. Wait for sometime until count become stable on display. Press set key for 3Sec for next parameter.



Next parameter is L-CAL. Remove load from the load cell & wait for sometime until count become stable on display. Press set key to save the values. Please power off instrument & power on again to save all parameters



## Working

- 1.Do all connection as shows in connection diagram and turn on the instrument.
- 2.Display shows current process weight in kg as per range and decimal point selection.
- 3.10VDC Excitation Voltage O/P is also provided at back terminal to drive load cell.
- 4.To TARE the weight press  Key for 2 Sec.
- 5.Press  Key Show Peak Value.
- 6.Peak Value Reset Press  Key First and Press  Key For 3 Sec.

**NOTE :**